

Product Bulletin

Issue/Date:	August 17 th , 2021	Bulletin Number:	AQ081721
		Product Line:	SL10-A Retrofit Kit & Driver
Topic:	Discontinue Retrofit Kit & Driver; 52397; 52076		

Dear Aquafine Customers,

The SL10-A system was discontinued June of 2016 as per bulletin AQ05162016 and has exceeded support period.

Due to supplier component obsolescence, Aquafine is no longer able to support the following:

- **52397** retrofit kit used to convert from electromagnetic to electronic driver
- **52076** replacement driver for the SL10-A.

UV lamps, sleeves and o-rings will continue to be supported for this product.

Replacement Option

For a replacement system for the SL10-A, check out the *Aquafine VL Series* product line. For more information contact your local RSM and/or download a copy of the brochure:

- 1) Login to the Trojan Technologies secure Industrial (Aquafine) Channel Partner portal at www.trojantechnologies.com and under the 'Secure Content' section
- 2) Click the "VL Series" tab and download a copy of the brochure.

Should you have any issues logging into the secure portal, please contact emarketing@trojantechnologies.com.

DAVID MORAIS | Product Manager

(519) 760-2310 *mobile*

dmorais@trojantechnologies.com

TROJAN TECHNOLOGIES